



MICHIGAN DEPARTMENT OF TRANSPORTATION
DIVISION OF HIGHWAYS
BRIDGE MAINTENANCE UNIT

ATTENTION _____

BRIDGE INSPECTION REPORT

TYPE OF INSPECTION: _____

COUNTY Union BRIDGE NUMBER _____ INSPECTION CYCLE _____
ROUTE Buffett Ln ACROSS _____ M. P. _____
LOCATION 0.15 MI. S. IGT Parrothead Dr.
DESCRIPTION 54" RCP with concrete headwall

PRESENT CONDITION Good INVENTORY RATING _____
INSPECTION DATE 11-6-34 OPERATING RATING _____
PRESENT POSTING Not Posted PROPOSED POSTING _____

COMPUTER UPDATE _____ ANALYSIS DATE _____
POSTING LETTER DATE _____ OTHER SIGNS PRESENT _____

ATTACH PHOTOGRAPH OF BRIDGE
SHOWING PRESENT POSTED STATUS

ALSO, SHOW BRIDGE ORIENTATION
(NORTH, SOUTH, EAST, OR WEST)

SIGN NOTICE ISSUED FOR	NUMBER REQUIRED
<u>No</u> WEIGHT LIMIT	_____
<u>No</u> SPECIAL PERMIT	_____
<u>No</u> DELINATORS	_____
<u>No</u> NARROW BRIDGE	_____
<u>No</u> ONE LANE BRIDGE	_____
<u>No</u> LOW CLEARANCE	_____

BRIDGE INSPECTION RECORD AND SUMMARY (PIPE AND ARCH CULVERTS)

DATE OF INSPECTION

BRIDGE NO.

COUNTY Union

DATE 11-6-24

ROUTE

Buffett Ln

CULVERT MATERIAL




CULVERT

YEAR BUILT

RECORD THE FOLLOWING ITEMS:

1. NUMBER, SIZE & TYPE OF CULVERT
2. LENGTH ALONG C/L ROADWAY
3. LENGTH ALONG C/L CULVERT
4. DISTANCE FROM CROWN ROADWAY TO BED
5. SKEW (if any)
6. APPROACH ROAD WIDTH (SHOW PAVED OR UNPAVED)
7. APPROACH SHOULDER WIDTH (SHOW LEFT OR RIGHT)
8. INCLUDE SKETCHES TO SHOW CULVERT SITUATION AND ROADWAY CLEARANCES THAT CANNOT BE DETAILED ON THIS SHEET

54" RCP
5'
50'
11'
70"
21'
7'



EVALUATION CODE: 0 - 2 CRITICAL, 3 & 4 POOR, 5 & 6 FAIR, 7 - 9 GOOD

INSPECTION ITEM		GRADE	BRIEF DESCRIPTION
FVAL	STRUCTURE CONDITION	5	
	WINGWALLS - RETAINING WALLS	5	
	HEADWALLS - TIEWALLS - FILLINGS	5	
ITEM #2	STRUCTURE ALIGNMENT - SETTLEMENT (INCLUDE SKEW)	5	
FVAL	CHANNEL & CHANNEL PROTECT	5	
	WATERWAY	5	
	ALIGNMENT	5	
FVAL	PROTECTION	5	
	SCOUR	5	
	GLOBE PROT. SET-UP	5	
FVAL	APPROACH ROADWAY CONDITION	5	
	ESTIMATED REMAINING LIFE (Years)	5	
	CHANNEL & CHANNEL PROTECT	5	
FVAL	CULVERT & RETAINING WALLS	5	
	WATERWAY ADEQUACY	5	
	APPROACH ROADWAY ALIGNMENT	5	
ITEM #12	FIELD SCOUR (SEE ITEM #12)	5	

IF PLAIN GULL BY

TEAMLEADER

[Signature]

INSPECTION REPORT

DATE

BY